
Conexión de paneles para bombas B4/H8 2200W (9 paneles de 330W y 45Voc)



ATENCIÓN

ES IMPRENSCINDIBLE COLOCAR UNA LLAVE TERMICA ENTRE LOS PANELES Y EL CONTROLADOR

PARA FACILITAR EL CONEXIONADO DE LOS BORNES.

OMANIPULAR LOS BORNES DEL CONTROLADOR CON ENERGIA EN EL SISTEMA TODA CONEXIÓN EN LOS BORNES TIENE QUE HACERSE CON LA LLAVE TERMICA BAJA CON LOS PANELES DESCONECTADOS

CUALQUIER DAÑO A LA PLACA POR MANIPULACION DE LOS BORNES (MOTOR, SENSORES, PANELES) TENIENDO EL SISTEMA ENERGIZADO, NO ESTARA CUBIERTO POR LA GARANTIA .

TOMA DE TIERRA: SE RECOMIENDA USAR UNA TOMA DE TIERRA PARA PROTEGER AL USUARIO EN CASO DE FUGAS EN 220V (VARILLA DE COBRE CONECTADO AL BORNE DE TIERRA)

IMPORTANTE

Los paneles colocarlos con inclinacion a 45º y orientados al Norte y sin sombras.

El Cable que va del Panel Solar al Controlador, con distancias hasta 50 mts - Cable Multifilar .

Si la distancia es mayor a 60 mts - Cable Multifilar 8mm.

El Cable que va del Controlador a la Bomba unir al chicote existente con un cable trifasico,

Con distancias hasta 40 mts - Cable Multifilar de 4 mm2 de sección (superplastico 3x4)

Si la distancia es de 40 a 80 mts - Cable Multifilar 6 mm2 de sección (superplastico 3x6)

Cable para los sensores, hasta 100M se recomienda de 1mm, de 100M a 250M 4mm, mas de 250M consultar.


IMPORTANTE: El equipo cuenta con un sensor flotador para el tanque o deposito conexcion (TH1-TH2) NC (normal cerrado) Una vez activo el sensor - este tardara 5 minutos en encender nuevamente PRESOSTATO: En el caso de usar presostato este se conectara en TH1-TH2 y tiene que ser normal cerrado

IMPORTANTE: Cuidado con las HORMIGAS. Sellar las entradas de la caja estanca de forma

de impedir la entrada de hormigas o insectos que dañen el circuito o cableado interno. DENTO DEL AGUA, LA BOMBA PUEDE ESTAR SUMERGIDA HASTA 90 MT.

EL DIAMETRO DE CAÑERÍA MINIMO ES DE 1 Y 1/4 PULGADA, DEPENDIENDO DE LA ALTURA MANOMETRICA (ALTURA DE ELEVACION + TRASLADO LATERAL) PUEDE SER DE DIAMETRO MAYOR (1 Y 1/2 O 2 PULGADAS)

NOTA: ESTA BOMBA ESTA DISEÑADA PARA BOMBEO DE AGUA LIMPIA. EL CONTENIDO DE ARENA, LIMO, TIERRA Y OTRAS PARTICULAS PUEDE DISMINUIR LA VIDA UTIL DE LA MISMA



Show	Diagnostic Content	Content Description	Processing Method	Re-Testing Time
E-A:	IPM protection	Output phase-to-phase short circuit or power IGPT damage	Check if the output terminals of the controller are properly connected; Check if the motor has faults If the fault is still repeated, please contact the seller or after-sales center.	
E-R2	Overcurrent protection	Excessive input or output current	Check the input power. Check if the motor and controller power match; Try to extend the acceleration time in parameter setting; Wait until the motor stops completely before starting; If the fault is still repeated, please contact the seller or after-sales center.	n 30 Seconds
E-D1	Drive failure	Drive hardware failure	Please contact the seller or after-sales center.	30 Seconds
Show	Diagnostic content	Content Description	Processing method	Re-Testing Time
E-N2	Water shortage protection	Water shortage protection in wells	Check well water level If the fault is still repeated, please contact the seller or after-sales center.	30 seconds, 30 minutes after 3 consecutive times
E-F1	Float switch	Reverse float connection when using dual float setting, or hardware failure	Exchange floats or swap X1 and X2 Check the float If the fault is still repeated, please contact the seller	30 Seconds
Show	Diagnostic content	Content Description	Processing method	Re-Testing Time
E-E2	Storage failure	EPROM memory corruption	Please contact the seller or after-sales center.	30 Seconds
E-UI	Low voltage protection	Bus voltage below 50V	Check the input power. If the fault is still repeated, please contact the seller or after-sales center.	30 Seconds
E-U2	Overvoltage protection	Bus voltage higher than 460V	Check the input power. If the fault is still repeated, please contact the seller or after-sales center.	30 Seconds
E-CH	Over temperature protection	The temperature inside the control box exceeds the set protection temperature	Check the installation environment of the controller; Check the radiator duct; If the fault is still repeated, please contact the seller or after-sales center.	30 Seconds
E-61	Stall protection	Controller motor parameters are not correct	Check whether the controller parameter Settings (P1, P2) are correct; If the fault is still repeated, please contact the seller or after-sales center.	30 Seconds
E-L2	Out-of-step protection	Insufficient starting voltage, too much fluctuation of AC power supply	Check the input power. If the fault is still repeated, please contact the seller or after-sales center.	30 Seconds
E-01	Current Offset	Controller current detection hardware failure	Please contact the seller or after-sales center.	30 Seconds
Е-П1	Out-of-phase protection	The motor is connected to one phase less or not connected to the motor or motor temperature protector protection	Check the input power Check the controller input terminal Check motor/water pump If the fault is still repeated, please contact the seller or after-sales center.	3 Minutes